

Manual with traverses 2

5552




Maximum lacquered detail: W1000 D2900mm

Hall dimensions: 12,950 x 4,500mm

Drying after surface preparation and polymerization: 1 zone oven-dryer

Manual painting: Cab open

Transport system: Manual upper TR



4320


Maximum lacquered detail: W1800 D7300mm

Hall dimensions: 16,240x16,640mm

Drying after surface preparation and polymerization: 1 zone oven-dryer

Manual painting: Cab open

Transport system: Manual upper TR



4120-1

Maximum lacquered detail: W1800 D7800mm

Hall dimensions: 60,000x40,000mm

Surface preparation: 2-stage automatic car wash

Drying after surface preparation: 6 zone dryer

Manual painting: Pass-through tunnel cabin KPT1

Polymerization: 6 zone oven

Transport system: Manual Top



4120-2

Maximum lacquered detail: W1800 D7800mm

Hall dimensions: 60,000x40,000mm


Surface preparation: 2-stage automatic car wash

Drying after surface preparation: 6 zone dryer

Manual painting: Pass-through tunnel cabin KPT1

Polymerization: 6 zone oven

Transport system: Manual Top



9994

Maximum lacquered detail: W1800 D7800mm

Hall dimensions: 25,000x24,800mm

Surface preparation: 2-stage automatic car wash

Drying after surface preparation and polymerization: 2 zone oven-dryer

Manual painting: Pass-through tunnel cabin KPT1

Transport system: Manual Top

